# Jabra Pro 930 Mono

How do I perform a soft reset of my Jabra Pro 900 Series headset?

To perform a soft reset of your Jabra Pro 900, follow these steps:

1. Unplug the base power supply from the power outlet.
2. Remove the headset from the base.
3. Turn the headset off by pressing and holding (3-5 seconds) the **Multi-function** button until the headset LED blinks rapidly and then turns off. Then release the button.

Multi-function button

LED

4. Place the headset back onto the base.
5. Plug the base power supply into the power outlet again. The soft reset is now completed.