

Jabra Elite Active 75t - Sienna

How do I resolve connection issues with the left earbud of my Jabra Elite 75t/Elite Active 75t?

A soft reset may address issues such as lost connection in the left earbud of your Jabra Elite 75t/Elite Active 75t.

To perform a soft reset, follow these steps.

- 1. Remove both earbuds from the charging case.
- 2. Ensure the earbuds are paired and connected with your mobile device.
- 3. Place the left earbud in the charging case and keep the lid open.
- 4. Wait for the LED on the left earbud to flash red while it is still in the charging case.
 - If the LED does not flash red, try cleaning the pins and poles on the charging case.
- 5. Leave the left earbud in the charging case with the lid open for at least 10 seconds.
- 6. Remove the left earbud to re-establish connection with the right earbud.