

Jabra Evolve2 55 - Link390a UC Mono


How do I charge my Jabra Evolve2 55?

You can charge your headset using the supplied USB charging cable or the optional charging stand. It takes approximately 2 hours to fully charge the battery. When fully charged, the battery life is up to 18 hours. If out of battery, charging the headset for 30 minutes will give up to 9 hours of battery life.

Using the USB charging cable

Plug the USB charging cable into the USB-C charging port on the right earcup and an available USB port on your computer. We recommend you use the supplied Jabra charging cable, although it is possible to use a compatible charger.


Right earcup



Using the charging stand (optional accessory)

Use the supplied USB charging cable to connect the charging stand to a powered USB port on your computer, and then dock the headset on the charging stand. Alternatively, plug the charging stand into a powered USB power supply. The status LED on the headset will flash white briefly to indicate the headset has been correctly docked with the charging

stand.



Status LED on right earcup

- A solid green LED indicates the battery is full.
- A solid yellow LED indicates the battery is medium.
- A solid red LED indicates the battery is low.
- A flashing red LED indicates the battery is critically low.